

Tuesday, 15 May 2018

## **KANMANTOO PRIMARY CRUSHER BEARING REPLACEMENT**

---

Hillgrove Resources Limited (ABN 73 004 297 116) (ASX: HGO) ("Hillgrove") wishes to advise that a mechanical failure has occurred with its primary crusher which will result in a temporary stoppage in production.

Work has commenced on the replacement of the failed bearing, which is anticipated to take between seven to ten days to complete. The Company will take this opportunity to bring forward other planned preventative maintenance, including a SAG Mill girth gear rotation. Undertaking this work now will reduce the quarterly scheduled shut down in July 2018 by three days.

The primary crusher has been utilised continuously since 2013 without any major maintenance issues and the bearing replacement will return the crusher to full working order.

Importantly, mining operations continue at full capacity and this outage is not expected to have a material impact and 2018 annual guidance remains unchanged.

**For more information contact:**

Mr Steven McClare  
CEO & Managing Director  
Tel: +61 (0)8 7070 1698

Mr Paul Kiley  
CFO and Company Secretary  
Tel: +61 (0)8 7070 1698