REEDY LAGOON CORPORATION LIMITED

ABN 41 006 639 514

**ASX : RLC**

1 April 2021

# Gold for Reedy Lagoon at Burracoppin, Western Australia

Orientation soil sampling has identified strong gold anomalies at the Burracoppin Gold project in Western Australia.

Soil sampling has identified areas with peak values of greater than 30 ppb gold (background values are considered to be 2 ppb gold or less).

One of the anomalies occurs on a single traverse over sandy soils in an area devoid of any known past sampling. The peak value of 36 ppb gold is flanked by samples with greater than 5 ppb gold that extends for 400 metres along the traverse line (refer to the image below). Portable XRF readings of the samples provide an indication that the anomalous gold samples have elevated arsenic and there is elevated copper indicated in samples a few hundred meters to the east. These data suggest the gold results are not an artifact of the weathering environment.




Another anomalous area is associated with past sampling and includes the area around a RAB hole (L18) drilled to 14 metres depth by gold prospectors in 1994 and the nearby Lady Janet mine area located about 1.5 kilometres to the north west (refer ASX release 29 July 2020).

Sampling will recommence in the area to follow-up the anomalies identified and to extend reconnaissance sampling over targeted areas within the project area including the recently granted E70/5544 tenement. Additional assay of the samples recovered to date will be undertaken to acquire geochemical information for the purpose of assessing pathfinder elements and better understanding the provenance of the samples.

The Burracoppin Gold project is within exploration licences E70/4941, E70/5467 and E70/5544. The tenements are registered in the name of Bullamine Magnetite Pty Ltd a wholly owned subsidiary company of RLC. E70/5544 was granted on 23 March 2021.

Initial focus of exploration includes a structural feature, the Yandina Shear Zone, and areas adjacent to it.







Authorised for release on behalf of the Company.


Geof Fethers, Managing Director
Telephone: (03) 8420 6280
reedylagoon.com.au
Reedy Lagoon Corporation Limited
P O Box 2236, Richmond VIC 3121

*The information in this report that relates to Exploration Results is based on information compiled by Geof Fethers who is a member of the Australian Institute of Mining and Metallurgy (AusIMM). Geof Fethers is a director of the Company and has sufficient experience which is relevant to the style of mineralisation and type of deposit under consideration and to the activity which he is undertaking to qualify as a Competent Person as defined in the 2012 Edition of the "Australasian Code for the Reporting of Exploration Results, Mineral Resources and Ore Reserves (the JORC Code). Geof Fethers consents to the inclusion in the report of the matters based on his information in the form and context in which it appears. Where Exploration Results have been reported in earlier RLC ASX releases referenced in this report, those releases are available to view on the INVESTORS page of reedylagoon.com.au. The Company confirms that it is not aware of any new information or data that materially affects the information included in those earlier releases. The Company confirms that the form and context in which the Competent Person's findings are presented have not been materially modified from the original market announcement.*

---

Attachments:

Table 1. Burracoppin Gold project - JORC 2012 sampling techniques and data.

Table 2. Burracoppin Gold project - JORC 2012 reporting of exploration results.

Table 3. Soil sample assay data.

## Table 1 Burracoppin Gold Project - JORC 2012 Sampling techniques and data

(Criteria in this section apply to all succeeding sections.)

| Criteria | JORC Code explanation | Commentary |
|---|---|---|
| *Sampling techniques* | • *Nature and quality of sampling (eg cut channels, random chips, or specific specialised industry standard measurement tools appropriate to the minerals under investigation, such as down hole gamma sondes, or handheld XRF instruments, etc). These examples should not be taken as limiting the broad meaning of sampling.*<br>• *Include reference to measures taken to ensure sample representivity and the appropriate calibration of any measurement tools or systems used.*<br>• *Aspects of the determination of mineralisation that are Material to the Public Report.*<br>*In cases where 'industry standard' work has been done this would be relatively simple (eg 'reverse circulation drilling was used to obtain 1 m samples from which 3 kg was pulverised to produce a 30 g charge for fire assay'). In other cases more explanation may be required, such as where there is coarse gold that has inherent sampling problems. Unusual commodities or mineralisation types (eg submarine nodules) may warrant disclosure of detailed information.* | • Soil Sampling: Samples were collected at 50 metre intervals along parallel traverse lines orientated to cross expected mineralisation trends. Sample traverses were mostly wide spaced as is appropriate for the early stage orientation objectives of the sampling. At each sample site a standard protocol was used to collect a representative sample comprised of between 100 and 200 g of minus 200 micron sized grains for delivery to testing laboratories. Field notes record land form and sample texture.<br>• The soil sampling protocol used at all sites maximises sample representivity and site notes aid interpretation of results.<br>• For assay, an unpulverized 25 g aliquot was taken by the assay laboratory from each sample as collected (no further pre-treatment at laboratory) for aqua regia digestion and low level detection gold assay (DL 0.1 ppb Au) – AR25/eMS.<br>In addition, a 5 g aliquot was used for preliminary and indicative analysis by XRF for the purpose of assessing whether the method can be used to select samples which can be eliminated from further analysis. |
| *Drilling techniques* | • *Drill type (eg core, reverse circulation, open-hole hammer, rotary air blast, auger, Bangka, sonic, etc) and details (eg core diameter, triple or standard tube, depth of diamond tails, face-sampling bit or other type, whether core is oriented and if so, by what method, etc).* | • No drilling reported in this release |
| *Drill sample recovery* | • *Method of recording and assessing core and chip sample recoveries and results assessed.*<br>• *Measures taken to maximise sample recovery and ensure representative nature of the samples.*<br>• *Whether a relationship exists between sample recovery and grade and whether sample bias may have occurred due to preferential loss/gain of fine/coarse material.* | • No drilling reported in this release |
| *Logging* | • *Whether core and chip samples have been geologically and geotechnically logged to a level of detail to support appropriate Mineral Resource estimation, mining studies and metallurgical studies.*<br>• *Whether logging is qualitative or quantitative in nature. Core (or costean, channel, etc) photography.* | • Landform and sample medium was recorded for each sample<br>• No logging reported in this release<br>• No logging reported in this release |

| Criteria | JORC Code explanation | Commentary |
|---|---|---|
| | • *The total length and percentage of the relevant intersections logged.* | |
| *Sub-sampling techniques and sample preparation* | • *If core, whether cut or sawn and whether quarter, half or all core taken.*<br>• *If non-core, whether riffled, tube sampled, rotary split, etc and whether sampled wet or dry.*<br>• *For all sample types, the nature, quality and appropriateness of the sample preparation technique.*<br>• *Quality control procedures adopted for all sub-sampling stages to maximise representivity of samples.*<br>• *Measures taken to ensure that the sampling is representative of the in situ material collected, including for instance results for field duplicate/second-half sampling.*<br>• *Whether sample sizes are appropriate to the grain size of the material being sampled.* | • Not applicable<br>• The samples were supplied as collected to the laboratory for assay.<br>• Sample prep was completed in the field (sieved to minus 200 micron). The samples were not crushed or pulverised. This minimises contamination risk. The sample preparation is appropriate.<br>• The only sub-sampling undertaken on the samples was performed by the laboratory (Intertek Genalysis, Perth) when taking the 25 g aliquot for the assay procedure. The laboratory has QC procedures in place which include systematic insertions of duplicate, blank and CRM samples.<br>• CRM samples were also inserted during field collection: randomly at an achieved rate of 1 in 24 (target is 1 in 20).<br>• Duplicate samples were collected in the field in order to measure the representivity of the samples (subject to an assumption of the laboratory's effectiveness in assaying the samples). Target duplicate sample rate is 3 per 100, the achieved rate was 1 per 87. Results of the duplicate samples are consistent with the samples being representative.<br>• The 25 g sample size was appropriate for the orientation aspect of the program. Significantly smaller sample sizes have been found appropriate for representative gold assay of soil samples from the Yilgarn. |
| *Quality of assay data and laboratory tests* | • *The nature, quality and appropriateness of the assaying and laboratory procedures used and whether the technique is considered partial or total.*<br>• *For geophysical tools, spectrometers, handheld XRF instruments, etc, the parameters used in determining the analysis including instrument make and model, reading times, calibrations factors applied and their derivation, etc.*<br>• *Nature of quality control procedures adopted (eg standards, blanks, duplicates, external laboratory checks) and whether acceptable levels of accuracy (ie lack of bias) and precision have been established.* | • The nature and quality of the assaying and laboratory procedures used are considered appropriate.<br>• Samples were submitted to Intertek Genalysis, Perth for gold assay by aqua regia digestion and low level detection gold assay (DL 0.1 ppb Au) – AR25/eMS.<br>• Sample analysis by XRF was performed by Portable Spectral Services (PSS), an independent laboratory, using a Bruker CTX800 portable countertop XRF. Quality assurance and quality control procedures at PSS include insertions of $SiO_2$ and OREAS 45d CRMs to validate the instrument's onboard calibration. XRF results are not material to the report but are referenced.<br>• Quality assurance and quality control procedures at Intertek include insertions of duplicate, blank and CRM samples. External laboratory checks have not been conducted. No issues with accuracy or precision have been identified. |

| Criteria | JORC Code explanation | Commentary |
|---|---|---|
| *Verification of sampling and assaying* | • *The verification of significant intersections by either independent or alternative company personnel.*<br>• *The use of twinned holes.*<br>• *Documentation of primary data, data entry procedures, data verification, data storage (physical and electronic) protocols.*<br>• *Discuss any adjustment to assay data.* | • Due to the early stage of exploration no verification of significant assay results has been undertaken.<br>• No drilling reported in this release.<br>• Data is received from the laboratory in both hardcopy and digital format, it is entered into digital spreadsheets.<br>• No adjustments have made to assay data. |
| *Location of data points* | • *Accuracy and quality of surveys used to locate drill holes (collar and down-hole surveys), trenches, mine workings and other locations used in Mineral Resource estimation.*<br>• *Specification of the grid system used.*<br>• *Quality and adequacy of topographic control.* | • No drilling or Mineral Resource estimation reported.<br>• Sample location data determined by handheld GPS with accuracy +_5m<br>• Grid system is GDA94, MGA Zone 50 |
| *Data spacing and distribution* | • *Data spacing for reporting of Exploration Results.*<br>• *Whether the data spacing and distribution is sufficient to establish the degree of geological and grade continuity appropriate for the Mineral Resource and Ore Reserve estimation procedure(s) and classifications applied.*<br>• *Whether sample compositing has been applied.* | • Samples were collected at 50 m spacings along traverse lines orientated east west to be nominally orthogonal to interpreted mineralisation trends. Traverse line separations vary between 200 m (closest) to single lines.<br>• No Mineral Resource or Ore Reserve estimation procedure(s) and classifications are reported on.<br>• No sample compositing has been applied. |
| *Orientation of data in relation to geological structure* | • *Whether the orientation of sampling achieves unbiased sampling of possible structures and the extent to which this is known, considering the deposit type.*<br>• *If the relationship between the drilling orientation and the orientation of key mineralised structures is considered to have introduced a sampling bias, this should be assessed and reported if material.* | • Traverse lines orientated east west to be nominally orthogonal to interpreted mineralisation trends.<br>• No drilling reported in this release. |
| *Sample security* | • *The measures taken to ensure sample security.* | • All samples were collected and transported to the laboratory by a person contracted to the Company. A chain of control was maintained from the field to the laboratory. |
| *Audits or reviews* | • *The results of any audits or reviews of sampling techniques and data.* | • Data has been informally reviewed by an independent consultant geochemist. |

## Table 2 Burracoppin Gold Project - JORC 2012 Reporting of exploration results.

(Criteria listed in the preceding section also apply to this section.)

| Criteria | JORC Code explanation | Commentary |
|---|---|---|
| *Mineral tenement and land tenure status* | • *Type, reference name/number, location and ownership including agreements or material issues with third parties such as joint ventures, partnerships, overriding royalties, native title interests, historical sites, wilderness or national park and environmental settings.*<br>• *The security of the tenure held at the time of reporting along with any known impediments to obtaining a licence to operate in the area.* | • Exploration Licences 70/4941, 70/5467 and 70/5544 are located near the township of Merredin in southwest Western Australia.<br>• The registered title holder is Bullamine Magnetite Pty Ltd a wholly owned subsidiary of Reedy Lagoon Corporation Limited ("RLC"),<br>• Land ownership is mostly private.<br>• Ballardong People Native Title determination application – WAD 6181/1998 is current over all non-private land.<br>• A heritage agreement has been entered into which sets out protocols for clearance surveys required to gain consents for field operations.<br>• Access for surface sampling is arranged by agreement with land owners and formal access and compensation agreements with land owners are required prior to any drilling and other intensive activities – these will be negotiated as required.<br>• The tenements are all granted, in good standing and there are no known impediments to conducting further soil sampling programs. |
| *Exploration done by other parties* | • *Acknowledgment and appraisal of exploration by other parties.* | • Limited exploration has been conducted within the project area.<br>Enterprise Metals (2010 – 2013) conducted soil and rock chip sampling, including in the Lady Janet area, and drilling.<br>Prospectors drilled shallow RAB holes in the Lady Janet area in 1994<br>Cambrian Resources conducted some drilling in 1985. |
| *Geology* | • *Deposit type, geological setting and style of mineralisation.* | • The project area is situated in the NE margin of the Archaean Yilgarn Craton, approximately 5 kms E of Merredin, Western Australia.<br>• A regional shear traverses the project area from north to south (Yandina Shear Zone).<br>• Gold mineralisation associated with/derived from gold enriched magmas sourced from metasomatized mantle is targeted. |
| *Drill hole Information* | • *A summary of all information material to the understanding of the exploration results including a tabulation of the following information for all Material drill holes:*<br>  ○ *easting and northing of the drill hole collar*<br>  ○ *elevation or RL (Reduced Level – elevation above sea level in metres) of the drill hole collar* | • No drilling reported in this release. |

| Criteria | JORC Code explanation | Commentary |
|---|---|---|
| | ○ *dip and azimuth of the hole*<br>○ *down hole length and interception depth*<br>○ *hole length.*<br>• *If the exclusion of this information is justified on the basis that the information is not Material and this exclusion does not detract from the understanding of the report, the Competent Person should clearly explain why this is the case.* | |
| *Data aggregation methods* | • *In reporting Exploration Results, weighting averaging techniques, maximum and/or minimum grade truncations (eg cutting of high grades) and cut-off grades are usually Material and should be stated.*<br>• *Where aggregate intercepts incorporate short lengths of high grade results and longer lengths of low grade results, the procedure used for such aggregation should be stated and some typical examples of such aggregations should be shown in detail.*<br>• *The assumptions used for any reporting of metal equivalent values should be clearly stated.* | • No weighting, averaging or sample aggregation has been applied.<br>• No metal equivalents used. |
| *Relationship between mineralisation widths and intercept lengths* | • *These relationships are particularly important in the reporting of Exploration Results.*<br>• *If the geometry of the mineralisation with respect to the drill hole angle is known, its nature should be reported.*<br>• *If it is not known and only the down hole lengths are reported, there should be a clear statement to this effect (eg 'down hole length, true width not known').* | • No drilling reported in this release. |
| *Diagrams* | • *Appropriate maps and sections (with scales) and tabulations of intercepts should be included for any significant discovery being reported These should include, but not be limited to a plan view of drill hole collar locations and appropriate sectional views.* | • No drilling reported in this release. |
| *Balanced reporting* | • *Where comprehensive reporting of all Exploration Results is not practicable, representative reporting of both low and high grades and/or widths should be practiced to avoid misleading reporting of Exploration Results.* | • All relevant assay data is provided in appendix 1 to the report. |
| *Other substantive exploration data* | • *Other exploration data, if meaningful and material, should be reported including (but not limited to): geological observations; geophysical survey results; geochemical survey results; bulk samples – size and method of treatment; metallurgical test results; bulk density, groundwater, geotechnical and rock characteristics; potential deleterious or contaminating substances.* | • Additional exploration data will be reported when it is acquired. |
| *Further work* | • *The nature and scale of planned further work (eg tests for lateral* | • The report describes an initial orientation and reconnaissance soil |

| Criteria | JORC Code explanation | Commentary |
| --- | --- | --- |
| | *extensions or depth extensions or large-scale step-out drilling).*<br>• *Diagrams clearly highlighting the areas of possible extensions, including the main geological interpretations and future drilling areas, provided this information is not commercially sensitive.* | sampling program. The report includes a description of anomalous results and that further sampling is required including further sampling to follow up the anomalies.<br>• It is too early to show areas of possible extensions. |

## Table 3 Burracoppin Gold Project - Soil sample assay data.

| ELEMENTS | EAST | NORTH | Au_1 | ELEMENTS | EAST | NORTH | Au_1 |
|---|---|---|---|---|---|---|---|
| UNITS | MGA94 zone 50 | MGA94 zone 50 | ppb | UNITS | MGA94 zone 50 | MGA94 zone 50 | ppb |
| ASSAY_CODE | | | AR25/eMS | ASSAY_CODE | | | AR25/eMS |
| DETECTION_LIMIT_LOWER | | | 0.1 | DETECTION_LIMIT_LOWER | | | 0.1 |
| **SAMPLE NO** | **EAST** | **NORTH** | **Au_1_ppb** | **SAMPLE NO** | **EAST** | **NORTH** | **Au_1_ppb** |
| BS019 | 640750 | 6524000 | 2.2 | BS063 | 641250 | 6523600 | 4.2 |
| BS020 | 640800 | 6524000 | 3.7 | BS064 | 641300 | 6523600 | 7.5 |
| BS021 | 640850 | 6524000 | 4.2 | BS065 | 641350 | 6523600 | 6.2 |
| BS022 | 640900 | 6524000 | 1.3 | BS066 | 641400 | 6523600 | 0.6 |
| BS023 | 640950 | 6524000 | 1.8 | BS067 | 641450 | 6523600 | 0.4 |
| BS024 | 641000 | 6524000 | 2.2 | BS068 | 641500 | 6523600 | 0.4 |
| BS025 | 641050 | 6524000 | 2.3 | BS069 | 641200 | 6522800 | 3.8 |
| BS027 | 641100 | 6524000 | 2.8 | BS070 | 641250 | 6522800 | 7.2 |
| BS028 | 641150 | 6524000 | 1.1 | BS071 | 641300 | 6522800 | 2.6 |
| BS029 | 641200 | 6524000 | 0.2 | BS072 | 641350 | 6522800 | 6.4 |
| BS030 | 641250 | 6524000 | X | BS073 | 641400 | 6522800 | 4 |
| BS031 | 641300 | 6524000 | 0.3 | BS074 | 641450 | 6522800 | 3.9 |
| BS033 | 641400 | 6524000 | X | BS075 | 641500 | 6522800 | 2.9 |
| BS034 | 640750 | 6523800 | 1.4 | BS076 | 641550 | 6522800 | 3.2 |
| BS035 | 640800 | 6523800 | 1.5 | BS077 | 641600 | 6522800 | 3.2 |
| BS036 | 640850 | 6523800 | 3.8 | BS078 | 641650 | 6522800 | 2.5 |
| BS037 | 640900 | 6523800 | 4.5 | BS079 | 641700 | 6522800 | 8.9 |
| BS038 | 640950 | 6523800 | 3.9 | BS080 | 641750 | 6522800 | 35.4 |
| BS039 | 641000 | 6523800 | 3.3 | BS081 | 641800 | 6522800 | 2.1 |
| BS040 | 641050 | 6523800 | 4.1 | BS082 | 641850 | 6522800 | 0.6 |
| BS041 | 641100 | 6523800 | 4.6 | BS083 | 641900 | 6522800 | 0.6 |
| BS042 | 641150 | 6523800 | 3 | BS085 | 641950 | 6522800 | 0.7 |
| BS043 | 641200 | 6523800 | 1.3 | BS086 | 642000 | 6522800 | X |
| BS044 | 641250 | 6523800 | X | BS087 | 641200 | 6522600 | 4.3 |
| BS045 | 641300 | 6523800 | 0.2 | BS088 | 641250 | 6522600 | 5.1 |
| BS046 | 641350 | 6523800 | 0.1 | BS089 | 641300 | 6522600 | 5.7 |
| BS047 | 641400 | 6523800 | 0.3 | BS090 | 641350 | 6522600 | 4 |
| BS048 | 641450 | 6523800 | 0.2 | BS091 | 641400 | 6522600 | 3.2 |
| BS050 | 641550 | 6523800 | 0.5 | BS092 | 641450 | 6522600 | 2.6 |
| BS051 | 641600 | 6523800 | 0.3 | BS093 | 641500 | 6522600 | 2 |
| BS052 | 640750 | 6523600 | 1.3 | BS094 | 641550 | 6522600 | 3 |
| BS053 | 640800 | 6523600 | 3.3 | BS095 | 641600 | 6522600 | 1.4 |
| BS054 | 640850 | 6523600 | 4 | BS096 | 641650 | 6522600 | 4.2 |
| BS055 | 640850 | 6523601 | 3.6 | BS098 | 641700 | 6522600 | 2.9 |
| BS056 | 640900 | 6523600 | 3 | BS099 | 641750 | 6522600 | 2.5 |
| BS057 | 640950 | 6523600 | 1.5 | BS100 | 641800 | 6522600 | 2.5 |
| BS058 | 641000 | 6523600 | 2.3 | BS101 | 641850 | 6522600 | 1.5 |
| BS059 | 641050 | 6523600 | 1.4 | BS102 | 641900 | 6522600 | 0.9 |
| BS060 | 641100 | 6523600 | 1.3 | BS103 | 641950 | 6522600 | 0.4 |
| BS061 | 641150 | 6523600 | 1.9 | BS104 | 642000 | 6522600 | 0.3 |
| BS062 | 641200 | 6523600 | 5 | BS105 | 642050 | 6522600 | 0.4 |

| | | | |
|---|---|---|---|
| BS106 | 642100 | 6522600 | 0.5 |
| BS107 | 642150 | 6522600 | 0.3 |
| BS109 | 642200 | 6522600 | 0.7 |
| BS110 | 641200 | 6522400 | 0.9 |
| BS111 | 641250 | 6522400 | 1.3 |
| BS112 | 641300 | 6522400 | 1.1 |
| BS113 | 641350 | 6522400 | 1 |
| BS114 | 641400 | 6522400 | 1.2 |
| BS115 | 641450 | 6522400 | 1.8 |
| BS116 | 641500 | 6522400 | 2 |
| BS117 | 641550 | 6522400 | 1.6 |
| BS118 | 641600 | 6522400 | 4.3 |
| BS119 | 641650 | 6522400 | 8.6 |
| BS120 | 641700 | 6522400 | 8 |
| BS121 | 641750 | 6522400 | 5.3 |
| BS123 | 641800 | 6522400 | 1.6 |
| BS124 | 641850 | 6522400 | 0.8 |
| BS125 | 641900 | 6522400 | 2 |
| BS126 | 641950 | 6522400 | 2.8 |
| BS127 | 642000 | 6522400 | 0.9 |
| BS128 | 642050 | 6522400 | 0.5 |
| BS129 | 642100 | 6522400 | 0.6 |
| BS130 | 642150 | 6522400 | 0.6 |
| BS131 | 642200 | 6522400 | 0.4 |
| BS132 | 642250 | 6522400 | 0.7 |
| BS133 | 642300 | 6522400 | 0.8 |
| BS134 | 642350 | 6522400 | 0.9 |
| BS135 | 638050 | 6521600 | 1.4 |
| BS136 | 638100 | 6521600 | 1.8 |
| BS137 | 638150 | 6521600 | 0.5 |
| BS138 | 638151 | 6521600 | 0.5 |
| BS139 | 638200 | 6521600 | 1.1 |
| BS140 | 638250 | 6521600 | 0.8 |
| BS141 | 638300 | 6521600 | 0.8 |
| BS142 | 638350 | 6521600 | 0.7 |
| BS143 | 638400 | 6521600 | 0.6 |
| BS144 | 638450 | 6521600 | 0.7 |
| BS145 | 638500 | 6521600 | 0.7 |
| BS146 | 638550 | 6521600 | 0.7 |
| BS147 | 638600 | 6521600 | 0.3 |
| BS148 | 638650 | 6521600 | 0.5 |
| BS149 | 638700 | 6521600 | 0.3 |
| BS150 | 638750 | 6521600 | 0.9 |
| BS151 | 638800 | 6521600 | 0.6 |
| BS152 | 638850 | 6521600 | 0.9 |
| BS153 | 638900 | 6521600 | 0.9 |
| BS154 | 638950 | 6521600 | 1.2 |
| BS155 | 639000 | 6521600 | 0.7 |
| BS156 | 639050 | 6521600 | 1.6 |
| BS157 | 639100 | 6521600 | 1.3 |
| BS158 | 639150 | 6521600 | 1 |
| BS159 | 639200 | 6521600 | 1.1 |
| BS160 | 639250 | 6521600 | 1.8 |
| BS161 | 639300 | 6521600 | 1.5 |
| BS162 | 639350 | 6521600 | 1 |
| BS164 | 639400 | 6521600 | 0.7 |
| BS165 | 639450 | 6521600 | 0.7 |
| BS166 | 639500 | 6521600 | 0.5 |
| BS167 | 639550 | 6521600 | 0.6 |
| BS168 | 639600 | 6521600 | 0.4 |
| BS169 | 639601 | 6521600 | 0.5 |
| BS170 | 639650 | 6521600 | 0.3 |
| BS171 | 639700 | 6521600 | 0.6 |
| BS172 | 639750 | 6521600 | 0.8 |
| BS173 | 639800 | 6521600 | 0.8 |
| BS174 | 639850 | 6521600 | 0.9 |
| BS175 | 639900 | 6521600 | 0.3 |
| BS176 | 639950 | 6521600 | 0.3 |
| BS177 | 640000 | 6521600 | 0.3 |
| BS178 | 640050 | 6521600 | 0.6 |
| BS179 | 640100 | 6521600 | 0.6 |
| BS180 | 640150 | 6521600 | 0.5 |
| BS181 | 640200 | 6521600 | 0.7 |
| BS182 | 640250 | 6521600 | 1 |
| BS183 | 640300 | 6521600 | 0.5 |
| BS184 | 640350 | 6521600 | 0.3 |
| BS185 | 640400 | 6521600 | 0.3 |
| BS186 | 640450 | 6521600 | 0.5 |
| BS187 | 640500 | 6521600 | 0.6 |
| BS188 | 640550 | 6521600 | 0.2 |
| BS189 | 640600 | 6521600 | 0.2 |
| BS190 | 640650 | 6521600 | 0.2 |
| BS191 | 640700 | 6521600 | 0.7 |
| BS192 | 640750 | 6521600 | 1.5 |
| BS193 | 640800 | 6521600 | 1.9 |
| BS194 | 640850 | 6521600 | 2 |
| BS195 | 640900 | 6521600 | 2.4 |
| BS196 | 640950 | 6521600 | 1.4 |
| BS197 | 641000 | 6521600 | 1.3 |
| BS198 | 641050 | 6521600 | 2.4 |
| BS199 | 641100 | 6521600 | 1.8 |
| BS201 | 641200 | 6521600 | 1.3 |
| BS202 | 641250 | 6521600 | 1 |
| BS203 | 641300 | 6521600 | 0.7 |

| | | | |
|---|---|---|---|
| BS204 | 641350 | 6521600 | 0.6 |
| BS205 | 641400 | 6521600 | 1.2 |
| BS207 | 641450 | 6521600 | 0.3 |
| BS208 | 641500 | 6521600 | 0.3 |
| BS209 | 641550 | 6521600 | 0.2 |
| BS210 | 641600 | 6521600 | 0.3 |
| BS211 | 641650 | 6521600 | 0.4 |
| BS212 | 641700 | 6521600 | 1.2 |
| BS213 | 641750 | 6521600 | 0.7 |
| BS214 | 641800 | 6521600 | 1.9 |
| BS215 | 641850 | 6521600 | 2.1 |
| BS216 | 641900 | 6521600 | 1.2 |
| BS217 | 641950 | 6521600 | 3.6 |
| BS218 | 642000 | 6521600 | 1.8 |
| BS219 | 642050 | 6521600 | 3.3 |
| BS220 | 642100 | 6521600 | 0.7 |
| BS221 | 642150 | 6521600 | 0.7 |
| BS222 | 642200 | 6521600 | 0.7 |
| BS224 | 642250 | 6521600 | 1.5 |
| BS225 | 642300 | 6521600 | 1.1 |
| BS226 | 642350 | 6521600 | 1.1 |
| BS227 | 642400 | 6521600 | 0.8 |
| BS228 | 642450 | 6521600 | 0.3 |
| BS229 | 642500 | 6521600 | 0.8 |
| BS230 | 642550 | 6521600 | 1.1 |
| BS231 | 638000 | 6521200 | 1 |
| BS232 | 638050 | 6521200 | 0.6 |
| BS233 | 638100 | 6521200 | 1.1 |
| BS234 | 638150 | 6521200 | 1.2 |
| BS235 | 638200 | 6521200 | 1.1 |
| BS236 | 638250 | 6521200 | 0.6 |
| BS237 | 638300 | 6521200 | 0.7 |
| BS238 | 638350 | 6521200 | 0.5 |
| BS239 | 638400 | 6521200 | 0.7 |
| BS240 | 638450 | 6521200 | 1.1 |
| BS241 | 638500 | 6521200 | 1.1 |
| BS242 | 638550 | 6521200 | 0.6 |
| BS243 | 638600 | 6521200 | 0.6 |
| BS244 | 638650 | 6521200 | 0.7 |
| BS245 | 638651 | 6521200 | 0.7 |
| BS246 | 638700 | 6521200 | 0.5 |
| BS247 | 638750 | 6521200 | 0.3 |
| BS248 | 638800 | 6521200 | 0.3 |
| BS249 | 638850 | 6521200 | 0.2 |
| BS250 | 638900 | 6521200 | 0.4 |
| BS251 | 638950 | 6521200 | 0.4 |
| BS252 | 639000 | 6521200 | 0.7 |
| BS253 | 639050 | 6521200 | 0.7 |
| BS254 | 639100 | 6521200 | 0.9 |
| BS255 | 639150 | 6521200 | 0.6 |
| BS256 | 639200 | 6521200 | 0.9 |
| BS257 | 639250 | 6521200 | 0.8 |
| BS258 | 639300 | 6521200 | 0.4 |
| BS259 | 639350 | 6521200 | 0.5 |
| BS260 | 639400 | 6521200 | 0.5 |
| BS261 | 639450 | 6521200 | 0.4 |
| BS262 | 639500 | 6521200 | 1.3 |
| BS263 | 639550 | 6521200 | 0.9 |
| BS264 | 639600 | 6521200 | 6.9 |
| BS265 | 639650 | 6521200 | 0.6 |
| BS266 | 639700 | 6521200 | 0.4 |
| BS267 | 639750 | 6521200 | 0.4 |
| BS268 | 639800 | 6521200 | 0.7 |
| BS269 | 639850 | 6521200 | 0.9 |
| BS271 | 639900 | 6521200 | 0.7 |
| BS272 | 639950 | 6521200 | 0.7 |
| BS273 | 640000 | 6521200 | 0.5 |
| BS274 | 640050 | 6521200 | 0.4 |
| BS275 | 640100 | 6521200 | 0.4 |
| BS276 | 640150 | 6521200 | 0.4 |
| BS277 | 640200 | 6521200 | 0.9 |
| BS278 | 640250 | 6521200 | 0.5 |
| BS279 | 640300 | 6521200 | 0.4 |
| BS280 | 640350 | 6521200 | 0.5 |
| BS281 | 640400 | 6521200 | 0.3 |
| BS283 | 640450 | 6521200 | 0.7 |
| BS284 | 640500 | 6521200 | 0.8 |
| BS285 | 640550 | 6521200 | 1 |
| BS286 | 640600 | 6521200 | 0.9 |
| BS287 | 640650 | 6521200 | 0.5 |
| BS288 | 640700 | 6521200 | 1.4 |
| BS289 | 640750 | 6521200 | 0.5 |
| BS290 | 640800 | 6521200 | 1.3 |
| BS291 | 640850 | 6521200 | 1.9 |
| BS292 | 640900 | 6521200 | 2.3 |
| BS293 | 640950 | 6521200 | 0.9 |
| BS294 | 641000 | 6521200 | 1 |
| BS295 | 641050 | 6521200 | 0.9 |
| BS296 | 641100 | 6521200 | 0.8 |
| BS298 | 641200 | 6521200 | 0.2 |
| BS299 | 641250 | 6521200 | 0.6 |
| BS300 | 641300 | 6521200 | 0.2 |
| BS302 | 641400 | 6521200 | X |
| BS303 | 641450 | 6521200 | 0.1 |

| | | | |
|---|---|---|---|
| BS304 | 641500 | 6521200 | X |
| BS305 | 641550 | 6521200 | X |
| BS306 | 641600 | 6521200 | 0.1 |
| BS308 | 641650 | 6521200 | 0.5 |
| BS309 | 641700 | 6521200 | 0.3 |
| BS310 | 641750 | 6521200 | 0.2 |
| BS311 | 641800 | 6521200 | 0.3 |
| BS312 | 641850 | 6521200 | 0.2 |
| BS313 | 641900 | 6521200 | 0.4 |
| BS314 | 641950 | 6521200 | 5.1 |
| BS315 | 642000 | 6521200 | 5.8 |
| BS316 | 642050 | 6521200 | 4.6 |
| BS317 | 642100 | 6521200 | 0.4 |
| BS318 | 642150 | 6521200 | 0.3 |
| BS319 | 642200 | 6521200 | 0.6 |
| BS320 | 642250 | 6521200 | 0.6 |
| BS321 | 642300 | 6521200 | 0.6 |
| BS322 | 642350 | 6521200 | 0.5 |
| BS323 | 642400 | 6521200 | 0.5 |
| BS324 | 642450 | 6521200 | 0.4 |
| BS325 | 642500 | 6521200 | 0.5 |
| BS326 | 642550 | 6521200 | 0.7 |
| BS327 | 642000 | 6517600 | 0.3 |
| BS328 | 642050 | 6517600 | 0.2 |
| BS329 | 642100 | 6517600 | 0.3 |
| BS330 | 642150 | 6517600 | 0.1 |
| BS332 | 642200 | 6517600 | 0.4 |
| BS333 | 642250 | 6517600 | 0.4 |
| BS334 | 642300 | 6517600 | 0.3 |
| BS335 | 642350 | 6517600 | 2.3 |
| BS336 | 642400 | 6517600 | 1.1 |
| BS337 | 642450 | 6517600 | 0.3 |
| BS338 | 642500 | 6517600 | 0.4 |
| BS339 | 642550 | 6517600 | 0.5 |
| BS340 | 642600 | 6517590 | 0.2 |
| BS341 | 642650 | 6517600 | 0.2 |
| BS342 | 642700 | 6517600 | 0.3 |
| BS343 | 642750 | 6517600 | 0.4 |
| BS344 | 642800 | 6517600 | 0.4 |
| BS345 | 642850 | 6517600 | X |
| BS346 | 642900 | 6517600 | X |
| BS347 | 642950 | 6517600 | X |
| BS348 | 643000 | 6517600 | 0.1 |
| BS349 | 643050 | 6517600 | 0.3 |
| BS350 | 643100 | 6517600 | 0.5 |
| BS351 | 643150 | 6517600 | 0.4 |
| BS352 | 643151 | 6517600 | 0.3 |
| BS353 | 643200 | 6517600 | 0.3 |
| BS354 | 643250 | 6517600 | 0.4 |
| BS355 | 643300 | 6517600 | 0.1 |
| BS356 | 643350 | 6517600 | 0.4 |
| BS357 | 643400 | 6517600 | 0.7 |
| BS358 | 643450 | 6517600 | 0.4 |
| BS359 | 643500 | 6517600 | 0.8 |
| BS360 | 643550 | 6517600 | 0.4 |
| BS361 | 643600 | 6517600 | 0.5 |
| BS362 | 643650 | 6517600 | 1 |
| BS363 | 643700 | 6517600 | 1.2 |
| BS364 | 643750 | 6517600 | 0.2 |
| BS365 | 643800 | 6517600 | 0.4 |
| BS366 | 643850 | 6517600 | 0.5 |
| BS367 | 643900 | 6517600 | 1.4 |
| BS368 | 643950 | 6517600 | 0.5 |
| BS369 | 644000 | 6517600 | 0.2 |
| BS370 | 641100 | 6516400 | 2 |
| BS371 | 641150 | 6516400 | 1.6 |
| BS372 | 641200 | 6516400 | 0.8 |
| BS373 | 641250 | 6516400 | 1.3 |
| BS375 | 641300 | 6516400 | 2.3 |
| BS376 | 641350 | 6516400 | 1.2 |
| BS377 | 641400 | 6516400 | 1.4 |
| BS378 | 641450 | 6516400 | 1.7 |
| BS379 | 641500 | 6516400 | 0.8 |
| BS380 | 641550 | 6516400 | 0.8 |
| BS381 | 641600 | 6516400 | 0.9 |
| BS382 | 641650 | 6516400 | 0.3 |
| BS383 | 641700 | 6516400 | 0.5 |
| BS384 | 641750 | 6516400 | 0.3 |
| BS385 | 641800 | 6516400 | 0.4 |
| BS386 | 641850 | 6516400 | 0.3 |
| BS387 | 641900 | 6516400 | 0.2 |
| BS389 | 641950 | 6516400 | 0.5 |
| BS390 | 642000 | 6516400 | 0.4 |
| BS391 | 642050 | 6516400 | 0.4 |
| BS392 | 642100 | 6516400 | 0.4 |
| BS393 | 642150 | 6516400 | 0.4 |
| BS394 | 642200 | 6516400 | 0.3 |
| BS395 | 642250 | 6516400 | 0.3 |
| BS396 | 642300 | 6516400 | 0.3 |
| BS397 | 642350 | 6516400 | 0.2 |
| BS398 | 642400 | 6516400 | 0.2 |
| BS399 | 642450 | 6516400 | 0.4 |
| BS400 | 642500 | 6516400 | 0.2 |
| BS401 | 642550 | 6516400 | 0.3 |

| | | | |
|---|---|---|---|
| BS402 | 642600 | 6516400 | 0.2 |
| BS403 | 642650 | 6516400 | 0.1 |
| BS404 | 642700 | 6516400 | 0.2 |
| BS405 | 642750 | 6516400 | 0.2 |
| BS406 | 642800 | 6516400 | 0.1 |
| BS407 | 642850 | 6516400 | 0.3 |
| BS408 | 642900 | 6516400 | 0.8 |
| BS409 | 642950 | 6516400 | 0.3 |
| BS410 | 643000 | 6516400 | 0.5 |
| BS411 | 643050 | 6516400 | 0.2 |
| BS412 | 643100 | 6516400 | 0.7 |
| BS413 | 643150 | 6516400 | 0.2 |
| BS414 | 643200 | 6516400 | 0.2 |
| BS415 | 643250 | 6516400 | 0.4 |
| BS417 | 643300 | 6516400 | 0.3 |
| BS418 | 643350 | 6516400 | 0.4 |
| BS419 | 643400 | 6516400 | 0.4 |
| BS420 | 643450 | 6516400 | 1 |
| BS421 | 643500 | 6516400 | 0.3 |
| BS422 | 643550 | 6516400 | 0.4 |
| BS423 | 643600 | 6516400 | 0.3 |
| BS425 | 643650 | 6516360 | 0.4 |
| BS426 | 643700 | 6516400 | 0.4 |
| BS427 | 643750 | 6516400 | 0.4 |
| BS428 | 643800 | 6516400 | 0.2 |
| BS429 | 643850 | 6516400 | 0.5 |
| BS430 | 643900 | 6516400 | 0.3 |
| BS431 | 643950 | 6516400 | 1.3 |
| BS432 | 644000 | 6516400 | 0.7 |
| BS433 | 639250 | 6510000 | 0.5 |
| BS434 | 639300 | 6510000 | 0.6 |
| BS435 | 639350 | 6510000 | 0.6 |
| BS436 | 639400 | 6510000 | 0.2 |
| BS438 | 639501 | 6509996 | 1 |
| BS439 | 639550 | 6509997 | 0.2 |
| BS442 | 639700 | 6510000 | 0.2 |
| BS445 | 639850 | 6510000 | 0.2 |
| BS446 | 639900 | 6510000 | 0.2 |
| BS447 | 639950 | 6510000 | 0.2 |
| BS448 | 640000 | 6510000 | X |
| BS449 | 640050 | 6510000 | 0.2 |
| BS450 | 640100 | 6510000 | 0.1 |
| BS451 | 640150 | 6510000 | 0.8 |
| BS452 | 640200 | 6510000 | 0.7 |
| BS453 | 640250 | 6510000 | 0.6 |
| BS454 | 640300 | 6510000 | 0.1 |
| BS455 | 640350 | 6510000 | 0.3 |
| BS456 | 640397 | 6510000 | 0.2 |
| BS457 | 640396 | 6510000 | 0.1 |
| BS458 | 640450 | 6510000 | 0.2 |
| BS459 | 640500 | 6510000 | 0.3 |
| BS460 | 640550 | 6510000 | 0.1 |
| BS461 | 640600 | 6510000 | 0.1 |
| BS462 | 640650 | 6510000 | X |
| BS463 | 640700 | 6510000 | 0.2 |
| BS464 | 640750 | 6510000 | 0.4 |
| BS465 | 640800 | 6510000 | X |
| BS466 | 640850 | 6510000 | X |
| BS467 | 640901 | 6509998 | 0.1 |
| BS468 | 640950 | 6510002 | 0.2 |
| BS469 | 641000 | 6510000 | 0.5 |
| BS470 | 641050 | 6510000 | 0.9 |
| BS471 | 641100 | 6510000 | 1 |
| BS472 | 641150 | 6510000 | 1.2 |
| BS473 | 641200 | 6510000 | 1.2 |
| BS474 | 641250 | 6510000 | 0.5 |
| BS476 | 641300 | 6510000 | 0.3 |
| BS477 | 641350 | 6510000 | 0.4 |
| BS478 | 641400 | 6510000 | 0.5 |
| BS479 | 641450 | 6510000 | 1.1 |
| BS480 | 641500 | 6510000 | 0.7 |
| BS481 | 641550 | 6510000 | 1.3 |
| BS482 | 641600 | 6510000 | 1.4 |
| BS483 | 641650 | 6510000 | 1.3 |
| BS485 | 641700 | 6510000 | 2.5 |
| BS486 | 641750 | 6510000 | 7.9 |
| BS487 | 641800 | 6510000 | 10.2 |
| BS488 | 641850 | 6510000 | 36.4 |
| BS489 | 641900 | 6510000 | 11.7 |
| BS490 | 641950 | 6510000 | 10.8 |
| BS491 | 642000 | 6510000 | 3.9 |
| BS492 | 642050 | 6510000 | 4.3 |
| BS493 | 642100 | 6510000 | 5.9 |
| BS494 | 642150 | 6510000 | 5.8 |
| BS495 | 642200 | 6510000 | 2.9 |
| BS496 | 642250 | 6510000 | 3.4 |
| BS497 | 642300 | 6510000 | 2.3 |
| BS498 | 642350 | 6510000 | 1.6 |
| BS499 | 642400 | 6510000 | 1.4 |
| BS500 | 642450 | 6510000 | 1.7 |
| BS501 | 642500 | 6510000 | 1.4 |
| BS503 | 642550 | 6510000 | 2.4 |
| BS504 | 642600 | 6510000 | 0.5 |
| BS505 | 642650 | 6510000 | 0.5 |

| | | | |
|---|---|---|---|
| BS506 | 642700 | 6510000 | 0.9 |
| BS507 | 642750 | 6510000 | 0.6 |
| BS508 | 642800 | 6510000 | 0.4 |
| BS509 | 642850 | 6510000 | 0.2 |
| BS510 | 642900 | 6510000 | 0.5 |
| BS511 | 642950 | 6510000 | 0.2 |
| BS512 | 643000 | 6510000 | 0.2 |
| BS513 | 643050 | 6510004 | 0.2 |
| BS515 | 643100 | 6510000 | 0.2 |
| BS516 | 643150 | 6510000 | 0.2 |
| BS517 | 643200 | 6510000 | 0.2 |
| BS518 | 643250 | 6510000 | 0.2 |
| BS519 | 643300 | 6510000 | 0.4 |
| BS520 | 643350 | 6510000 | 0.3 |
| BS521 | 643400 | 6510000 | 0.2 |
| BS522 | 643450 | 6510000 | 0.4 |
| BS523 | 643500 | 6510000 | 0.3 |
| BS524 | 643550 | 6510000 | 0.3 |
| BS525 | 643600 | 6510000 | X |
| BS526 | 643650 | 6510000 | X |
| BS527 | 643700 | 6510000 | X |
| BS528 | 643750 | 6510000 | X |
| BS529 | 643800 | 6510000 | X |
| BS531 | 643850 | 6510000 | X |
| BS532 | 643900 | 6510000 | 0.5 |
| BS533 | 643950 | 6510000 | 0.4 |
| BS534 | 644000 | 6510000 | 0.2 |

| | | |
|---|---|---|
| X | Below detetection level | X |