

Ref: 379236

16 March 2015

ASX Market Announcements Australian Securities Exchange 20 Bridge Street SYDNEY NSW 2000

By Electronic Lodgement

Dear Sir/Madam

Thickener back on line at Langer Heinrich

Further to the announcement on 2nd March, Paladin Energy Ltd ("Paladin") wishes to advise that the pre-leach thickener that was reported damaged has been repaired and normal production was re-established by Friday 13 March. Lost production due to this event was as indicated at around 100,000lb. Revised guidance for FY15 will be provided at the end of March once overall production for the quarter is known.

Yours faithfully Paladin Energy Ltd

JOHN BORSHOFF
Managing Director/CEO